Service Bulletin

Bulletin No. 2014-65
OEM No. 2014-64

Circulate to: ☐ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

Wire Harness For Mercury Diesel 2.0L Long Block Replacement

Models Affected

Models Covered	Serial Number
2.0L 115 hp	88200000–88200999, 88500000–88500095
2.0L 130 hp	88205099–88207497
2.0L 150 hp	88220000–88222659
2.0L 170 hp	88230000–88232022

Scope

Worldwide

Situation

The service replacement 2.0L long block contains a new cam position and speed sensor. Due to these changes, when performing a long block change in the above engine serial number range, the existing engine wire harness needs to be replaced. Engine wire harness 8M0095332 must be ordered.

Parts Required

Qty.	Description	Part Number
1	Engine wire harness	8M0095332

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com