Hi-Performance MARINER OUTBOARDS

MERCURY PERFORMANCE OUTBOARDS

service bulletin

No. 94-5

Drive Shaft Corrosion on All Hi-Performance Gearcases

There have been a few reports from the field of difficulty in removing the water pump impeller from the chrome plated drive shaft on Hi-Performance outboards used in salt water environments.

It is recommended to coat the drive shaft in the impeller area and the impeller key with anti-corrosion grease (P/N 92-78376A1) during normal water pump service.

If the outboard is not used in saltwater, Mercury Hi-Performance still recommends the above service procedure for corrosion and rust protection and ease of service.

provided by http://www.crowleymarine.com