FORCE Outboards

service bulletin

No. 91-9

1988 and 1989 50 HP Parts Book Error

This bulletin is to advise you of a Part Number error in some of the 50 HP Parts Books. In Parts Books OB4193, OB4194, OB4252 (1988 50 HP) and OB4274, OB4275, OB4396 (1989 50HP). Illustration 18 on the gear housing page is incorrect, it now reads A458662. The correct number should be A485662. Please make the change in your parts books and retain this bulletin for handy reference.

provided by http://www.crowleymarine.com