MotorGuide
NEVER STOP.
motorguide.com

Service Bulletin

Bulletin No. 2009-01

Circulate to: ☑ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager


FW45 Wireless Lower Unit No Longer Available

Models Affected

All freshwater, wireless 45 models.

Description

Lower unit MBV39701T and armature MBV320712 are no longer available for service replacement.



40039

Lower unit MBV39701T

Correction Instructions

If lower unit MBV39701T requires replacement, replace the lower unit assembly and column.

Refer to the chart below for part replacement or consult the Mercury Electronic Parts Catalog.

Parts Required

Model	Replacement	Part Number
Freshwater, Wireless 45	Lower Unit	897345T84
	Armature	MCV320712

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com