MERCURY MARINER

Service Bulletin

Bulletin No. 2009-07

Circulate to: ☐ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

Throttle Roller No Longer Available (NLA) (2.5 Liter OptiMax XS and 3.0 Liter EFI/OptiMax)

Models Affected

Models Covered	Serial Number
200 XS 2.5 Liter OptiMax	0T235000–0T818180
200/225 3.0 Liter OptiMax	0T178500–0T800999
200/225/250 EFI 3.0 Liter	0T409000–0T800999
300 X EFI 3.0 Liter	0T235084–0T429939
3.0 Liter Sport Jet DFI	0E407100–Up

Situation

Throttle roller P/N 67748 3 is no longer available (NLA). This roller has been replaced with throttle roller and lever assemblies listed below.



40827

Throttle roller and lever assembly

Description	Part Number
2.5 Liter	850286A03
3.0 Liter	858851A03

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com