mercruiser
STERN DRIVES & INBOARDS


service bulletin

TO: SERVICE MANAGER ☐ MECHANICS ☐
PARTS MANAGER ☐

No. 92-11

A. TESTING THUNDERBOLT IV HEI IGNITION SYSTEM

This latest test diagram will be added to all Service Manuals at their next update. Use a voltmeter when making these tests. Do not use a test light.



NOTE 1: Early, large ignition modules did not have a replaceable wiring harness.

provided by http://www.crowleymarine.com