# service bulletin

TO: SERVICE MANAGER ☐ TECHNICIANS ☐
PARTS MANAGER ☐

**No. 96-2**

## Water In Fuel Module (WIF) Warning Light

### Models

MCM/MIE D7.3L/270 Diesel Engines


### Situation

The warning light on the Engine System Monitor Panel may not operate correctly.

### Correction


Change wire on WIF light on Engine System Monitor Panel as shown.

### Current Wiring Set Up




72432

### Correct Wiring Set Up




72432



provided by http://www.crowleymarine.com