mercruiser STERNDRIVES & INBOARDS

service bulletin

TO: SERVICE MANAGER ☐ TECHNICIANS ☐
PARTS MANAGER ☐

No. 98-8

NOTICE

Revised December 1998. Destroy October 1998 Bulletin Changes are underlined


New One Piece Oil Seal Carrier for Alpha One Generation II

Models


3.0L / 4.3L / 4.3LH / 4.3L EFI / 5.0L / 5.0L EFI / 5.7L / 5.7L EFI / 350 MAG MPI

Situation

The Alpha One Generation II oil seal carrier under the seawater pump in the lower gear housing is being changed. The change will replace the present two piece housing with a new one piece housing. The one piece housing will supercede the present housing, and will back fit to the first Alpha One Generation II built.




75972




75973

807929A1
One piece style oil seal carrier assembly



70501



75975

821759A4
Two piece style oil seal carrier assembly

Printed in U.S.A. - © 1998, Mercury Marine
provided by http://www.crowleymarine.com