Service Bulletin

Bulletin No. 2005-70
CMD 2005-10

Circulate to: ☐ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

Diesel Transom Assembly Parts Content Advisory

Models Affected

Application	Model	Model Number
CMD	Sterndrive	6411002N2
		6411002TS

Situation

All Diesel Transom Assembly boxes should include a standard seawater fitting. In the models affected by this Service Bulletin, a quick connect seawater fitting may have been included in the transom assembly box. A quick connect seawater fitting cannot be used with a standard seawater hose.

Solution

Order the correct seawater fitting.

Part Description	Part Number
Standard seawater fitting	22-43828



17950

Standard seawater fitting



17951

Quick connect seawater fitting

NOTE: *Some Diesel Transom Assembly boxes were shipped with a standard and a quick connect seawater fitting. If both seawater fittings were included in your transom assembly box, please discard the quick connect fitting.*

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com