MERCURY MerCruiser

Service Bulletin

Bulletin No. 2009-03
OEM No. 2009-01

Circulate to: ☑ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

Through-The-Transom Oil Drain System Removed from Certain MerCruiser Engines

Models Covered	Serial Number Or Year
4.3 MPI	1A343329 and above
5.0, 5.7, and 6.2 MPI	1A342186 and above
496 Mag and 496 Mag HO	1A349411 and above

NOTE: *This change does not affect Tow Sports models or carbureted sterndrive models.*

Situation

Production MerCruiser sterndrive MPI engines no longer include the through-the-transom oil drain system.

The oil drain system is available as an optional accessory kit.

Correction

Service affected models by pumping the engine oil out through the oil dipstick tube.

Part Number

Order the appropriate through-the-transom oil drain system accessory kit as desired.

Engine	Part number
3.0 kit	32-865277A02
4.3 kit	32-865278A04
5.0, 5.7, 6.2 and 496 kit	32-865281A02

Warranty

This bulletin provides service information only and has no warranty implications.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com