MERCURY Racing

service bulletin

PERFORMANCE OUTBOARDS

No. 2000-3

☑ WARRANTY INFORMATION ☐ SERVICE INFORMATION

2.5 EFI ECM Replacement

Models Affected

2000 Model Year 2.5 EFI units serial numbers 0G980967 through 0G981545

Problem

The ECU (Electronic Control Unit) does not accurately monitor engine block pressure.

Correction

Order a new ECU P/N 858891-14.
Return ECU with a warranty claim and the engine serial number attached to the ECU with either tape or tag to Mercury Racing at the following address.

Return ECU To:
Mercury Racing
Attn: Pete Coen
N7480 County Rd. UU
Fond du Lac, WI 54935-9585

Warranty Information

Complete warranty claim listing:

- Engine Serial Number
- Qty. 1 ECU P/N 858891-14
- UFO Code: 731-00
- Flat Rate Code: HI12
- Three Tenths (0.3) hour labor to R & R ECU.

Printed in U.S.A. - © 2000, Mercury Marine
provided by http://www.crowleymarine.com