FORCE Outboards

service bulletin

No. 92-15

Power Trim Indicator Kits - 1993

Power trim indicator kits for1993 Models of the 40 through 150 HP Force Outboard motors are available. The reason for the new kits is that the transom brackets have changed (and now have the industry-standard transom bolt pattern). These changes require the new kit for 1993 models.

The new kits are as follows:

- 40, 50, and 70 HP - 1993
  Trim Indicator 820540A 1
- 90, 120, and 150 HP - 1993
  Trim Indicator 820568A 1

Each kit contains stop and sender assemblies, trim gauge, cable, drilling template and attaching hardware.

These power trim kits cannot be used with older (1992 and prior) model outboards.

provided by http://www.crowleymarine.com