FORCE Outboards


service bulletin

No. 93-9

FLYWHEEL PULLER BOLTS P/N 10-40001149

Force 2,3,& 4 Cylinder Engines (Including Sport Jet) w/ Thunderbolt Ignition

There has been a running change on the puller bolt thread size on the flywheel during the 1992 model year. This change was on the Thunderbolt ignition flywheels only. The threads were changed from English (1/4-20) to Metric (M8). M8x50 bolts have been added to the Flywheel Puller Tool Kit (FT8948–1). Flywheel Puller Tools with date code of 11/15/93 or later will contain the M8x50 bolts. To update tools in your inventory, order qty. three (3) of part number 10-40001149 through your normal distribution center.



Puller Bolt P/N 10-40001149

provided by http://www.crowleymarine.com



provided by http://www.crowleymarine.com