MotorGuide®
NEVER STOP.
motorguide.com

Service Bulletin

Bulletin No. 2009-05R1

Circulate to: ☑ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

Tour Lowrance Sonar Conversion

Models Affected

NOTE: *Identify the Tour Pinpoint Edition model number first, then reference and note the correct replacement Tour Lowrance lower unit assembly and transducer cable.*

Model Number	Model Description	Lower Unit Description and Part Number
930010030	TR70PFBD 45" 24V	70 lb M899500T
930010150	TR70PFBD 45" 24V	
930010170	TR70PFBD 45" 24V	
930010210	TR70PFBD 45" 24V	
9BT42GCAF	TR82PFBD 45" 24V	82 lb M899352T
9BT42ZCAM	TR82PFBD 45" 24V	
9BT52GCAF	TR82PFBD 50" 24V	
9BT62HCAF	TR82PFBD 60" 24V	
9BX43GCAF	TR109PFBD 45" 36V	109 lb M899344T
9BX43ZCAM	TR109PFBD 45" 36V	
9BX53GCAF	TR109PFBD 50" 36V	
9BX63HCAF	TR109PFBD 60" 36V	

Situation

Tour Pinpoint Edition puck transducer lower units and parts will no longer be manufactured after 08/2009. There will not be a Lowrance sonar conversion kit to upgrade a Tour Pinpoint Edition puck or Tour nonpuck lower unit.

Replacement Instructions

Replace the Tour Pinpoint Edition lower unit assembly and transducer cable with the correct Tour Lowrance lower unit assembly and transducer cable.

Parts Required

Refer to the chart below for replacement parts or consult the Mercury Electronic Parts Catalog.

Lower Unit Part Number	Replacement Description	Replacement Part Number
M899500T	82 lb lower unit	879317T90
M899352T	82 lb lower unit	879317T90
M899344T	109 lb lower unit	879317T92

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com

NOTE: *Although the Tour Pinpoint Edition transducer cable appears identical to the new Lowrance transducer cable, the wires are configured differently in the Lowrance connector. The new Lowrance lower unit assembly is only compatible with a new Lowrance transducer cable. For a complete compatibility listing of all sonar units, go to www.motorguide.com.*

Part Description	Replacement Part Number
Lowrance transducer cable	879364T03

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com