MotorGuide NEVER STOP. motorguide.com

Service Bulletin

Bulletin No. 2009-06

Circulate to: ☑ Sales Manager ☐ Accounting ☑ Service Manager ☑ Technician ☑ Parts Manager

FW40 Lower Unit Change

Models Affected


Models Covered	Model Description
921310210	FW40FB 42" 12V

Description

To ensure the weight of the lower unit is distributed evenly across the mount, replace lower unit MPF397042 with lower unit MEF397072.


Correction Instructions

To determine which lower unit is on the trolling motor, refer to the images and descriptions below.



42243

Lower unit MPF397042



42244

Lower unit MEF397072

a - Lower unit MPF397042 – column screws into the lower unit commutator cap.

b - Lower unit MEF397072 – column screws into the lower unit magnet housing.

Refer to the chart below for part replacement or refer to the Mercury Electronic Parts Catalog.

Model	Replacement	Part Number
FW40FB 42" 12V	Lower Unit	MEF397072

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

provided by http://www.crowleymarine.com