mercruiser STERN DRIVES & INBOARDS

parts bulletin

QUICKSILVER® MARINE PARTS AND ACCESSORIES

TO: PARTS MANAGER ☐
SERVICE MANAGER ☐

△ = Revised 11-2-92

No. 92-8

A. REPLACEMENT PISTONS AND RING SETS

Model

MCM/MIE 4.3L and 5.7L Engines


Change

The latest replacement standard pistons (P/N 735-9686) for these engines use a different set of piston rings. The latest piston's oil ring groove is not as deep as the older piston.

Replacement Parts

The latest replacement piston will be shipped with a set of piston rings.

If piston rings only are required, refer to the drawings before ordering replacement piston ring sets from the chart.



Model	Old Piston P/N 735-9686 Ring Set	New Piston P/N 735-9686 Ring Set
4.3L	39-17464	39-801861
5.7L	△ 39-17464	39-801861

provided by http://www.crowleymarine.com