


Remote Control Handle Change - P/N 92744A2

Replacement curved handle P/N 92744A2 for 88688A-- Console Remote Control.

The original 30° bend replacement handle installed on the remote controls listed is not available. A new replacement 23° bend handle is available and is slightly taller than the original one. On Dual Console Controls, you may want to change both handles so they are the same height. The part number for the new handle is the same as the original handle part number.



52051